

Datakey – Product Change Notification

 PCN Number:
 20220331

 Notice Date:
 31 March 2022

Notification Subject: Product Change Notification (PCN)

Summary Description:

As a result of the ongoing supply chain challenges in the semiconductor industry, ATEK has qualified a second source for the 16 Kbit SPI EEPROM used in SST16Kb, SSX16Kb, SSB16Kb and SSP16Kb memory tokens. Like the existing qualified IC, the new IC meets all of the specifications in the Datakey SPI EEPROM Interface Specification.

Affected Products:	Part Numbers:
SSP16Kb 16 Kbit SPI EEPROM Plug Memory Token	614-0009-000A
SST16Kb 16 Kbit SPI EEPROM SlimLine Memory Token (all colors)	611-0101-00xA*
SSX16Kb 16 Kbit SPI EEPROM Ext. Length Memory Token (all colors)	611-0122-00xA*
SSB16Kb 16 Kbit SPI EEPROM Bar Memory Token (all colors)	611-0184-00xA*
Customized 16 Kbit SSX16Kb and SSM16Kb Memory Tokens	Varies

^{*}The "x" in the part number would be replaced by a number corresponding to the color of the key/token (0=black, 2=red, 4=yellow, 5=green, 6=blue, 8=gray).

Details of Notice:

The memory IC that has been used in the Datakey 16 Kbit SPI EEPROM memory tokens is still an active part but is currently out of stock and the manufacturer is quoting extremely long lead times. To ensure that customers of the above-mentioned Datakey memory tokens continue to be able to purchase these products, ATEK engineering has qualified a similar IC from a different manufacturer. As mentioned above, this newly-qualified IC is fully compatible with the <u>Datakey SPI EEPROM Interface Specification</u>. Tokens made with the newly-qualified IC have been tested using Datakey factory testers, Datakey Series III programmers (like the SlimLink III, BarLink III, etc.) and Datakey sample applications and have shown to be fully compatible. As a result, since there is no change in form, fit or function, there will be no changes made to the above part numbers. Tokens with date codes of 4-2 (corresponding to April 2022) and later may use either of the qualified ICs.

If you have any questions regarding this PCN, please contact the Datakey Customer Care Team.

Contact Information:

Customer Care Team +1 (800) 523-6996

+1 (800) 323-0990

+1 (218) 829-9797

CCT@datakey.com





Full listing of part numbers impacted by this PCN:

611-0101-000A

611-0101-002A

611-0101-004A

611-0101-005A

611-0101-006A

611-0101-008A

611-0122-000A

611-0122-002A

611-0122-004A

611-0122-005A

611-0122-006A

611-0122-008A

611-0122-010A

611-0184-000A

611-0184-002A

611-0184-008A

614-0009-000A

699-0078-008A

699-0080-002A 699-0126-002A

699-0135-000A

699-0169-000A

699-0169-002A

699-0169-003A

699-0169-004A

699-0169-005A

699-0169-006A

699-0169-008A

